ate		OCT 1 5 1945 HEADQUARTERS ARMY AIR FORCES
ato	3.7	WASHINGTON WASHINGTON
<b>+</b>		The state of the s
		MICOLING ALD OBER DEDODE
		MISSING HIR CREW REPORT
		IMPORTANT: This Report will be compiled in triplicate by each Army Air
7 3		Forces organization within 48 hours of the time an air crew
1.	. "	member is officially reported missing.
		VAR Station
1		ORGANIZATION: Location, by Name 111 ; Command or Air Force 8th
- B. J. T. T.		Group 306th Bomb (H) Squadron 423rd Bomb (H) Detachment
2		SPECIFY: Place of Departure Thurleigh, Eng Course as prescribed
		Target or Intended Destination Hanover; Type of Mission Heavy Bomb
. 3	5.	WEATHER CONDITIONS AND VISIBILITY AT TIME OF CRASH OR WHEN LAST REPORTED:
16. 4	34.1	Weather was clear and visibility excellent
4		GIVE: (a) Day 22 Month Oct Year 44; Time 1222; and Location Over North Sea
	1	of last known whereabouts of missing aircraft.
		(b) Specify whether aircraft was last sighted (); Last contacted by
		radio ( ); Forced down ( ); Seen to Crash (x); or Information not Avail-
the second	51/50	able (.)
5		AIRCRAFT WAS LOST, OR IS BELIEVED TO HAVE BEEN LOST, AS A RESULT OF: (Check
		only one) bnemy hircraft ( ); Enemy Anti-hircraft ( ); Other Circumstances
	,	as Follows: Aircraft collided in air with another of the same
1/		AIRCRAFT: Type, Model and Series B-17-G ; AAF Serial Number 43-37976
CONTRACTOR Y	100	The state of the s
	•	
C	•	Number (a) SW-022853 ; (b) SW-022932 ; (c) 41-56477 ; (d) SW-022687
		INSTALLED WEAPONS (Furnish below Make, Type and Serial Number);
PAGE.	•	* (a) g-1214296; (b) g-1214617; (c) g-1214566; (d) 1214267;
1.		(e) s-1214200 ; (f) s-1214325 ; (g) s-1214405 ; (hs-1214546 ;
10		(i) c_1214530 ; (j) c_1214540 ; (k) c_1214600 ; (1) c_1214287 ;
	'	(i) s-1214539; (j) s-1214540; (k) s-1214600; (1) s-1214287; (m); (n); (o); (p);
. 1	0.	THE PERSONS LISTED BELOW WERE REPORTED AS: (a) Battle Casualty
		or (b) NonoBebbbcobosumbbos
1	1.	NUMBER OF PERSONS ABOARD AIRCRAFT: Crew 9; Passengers 0; Total 9
	100	(Starting with Pilot, furnish the following particulars: If more than 11
	1	persons were aboard aircraft, list similar particulars on separate sheet
		and attach original to this form.)
		Name in Full Serial Current
1		Crew Position (Last Nume First) Rank Number Status
		1. Pilot-pilot Manuathis, Joseph B.III Capt 0-748205 MIA
		KIA 2. Pilot-Copilot Major 0-724784 MTA
4.1		WA 3. Navigator-Navigator M. Siler. Gorman W. 1st It 0-717524 MTA
		X/A 5. Aer. Gun-Top Turr Gun Maupin. John P. T/Set 39079641 WIA
4		KIA 6. Aer. Gun-Top Turr Gun Maupin, John P. T/Sgt 39079641 MTA
		KIA 1 Aer Gum-Ball Turr Gun-Tooke, Creston O. Jr. S/Sgt 13176302 MTA
EVER'S		VIA 8 - Rer. Fine Cum-Waist Gun. Kasmiersky, Joe A. S/Sgt 18186747 MIA
		XIA 9. Aer Gm-Teil Gm. MReimann, Carroll L. S/Sgt 37572550 MTA 1
		10.
	Ė,	11.
1	2.	IDENTIFY BELOW THOSE PERSONS WHO ARE BELIEVED TO HAVE LAST KNOWLEDGE OF AIR-
	112	CRAFT, AND CHECK APPROPRIATE COLUMN TO INDICATE BASIS FOR SAME:
	10	Check Only One Column
1.3.	7000	Contacted Saw
	1	Name in Full Serial by Last Saw Forced
	1	(Last Name First) Rank Humber Radio Sighted Crash Landing
	100	1. Brown, Harold (MMI) 1st Lt 0-764201 X
		2. 3.
1.6-		
S-SE	ava	ge (Over)
	ern=	

FOLLOWING STATEMENTS: (a) Parachutes were used les; (b) Persons were seen walking away from scene of crash ; or (c) Any other reason (Specify) ATTACH AERIAL PHOTOGRAPH, MAP, CHART, OR SKETCH, SHOWING APPROXIMATE LOCATION WHERE AIRCRAFT WAS LAST SEEN OR HEARD FROM. 15. ATTACH EYELITHESS DESCRIPTION OF CRASH, FORCED LANDING, OR OTHER CIRCUM-STANCES PERTAINING TO MISSING AIRCRAFT. 16. GIVE NAME, RANK AND SERIAL NUMBER OF OFFICER IN CHARGE OF SEARCH, IF ANY, INCLUDING DESCRIPTION AND EXTENT Air Sea Rescue (unit unknown) conducted search and picked up three members of other aircraft involved in collision. (one man is still alive) dionavio .Date of Report .. 25 October 1944 Commission of a second of the distribution of the Compared to the state of the state of (Signature of ROBERT F. MORRIS. 17. REMARKS OR EYEWITNESS STATEMENTS: 1st Lt., Air Corps. Asst. Adjutant. Asst. Adjutant. 100 Sec. 607 \* Notice College ( College) ( Col icontoniisa. Etitorii (et 23 a O street in say Y 2 major - Translation Copie divided by Misself and A Translation of the Copie of The second secon ं भारतिस्थानी ALT MIGGINST TO THE THE STATE OF STATE And the state of t ness cartain and the second confidence in a company of Burney and the state of the sta Country discovered in forces of the

GROUP	306th Bomb Go (H	5Q 423 Bomb S	d/C	No. 4	3-37976 <sup></sup>	MISSI	ON DATE 2	2/10/44.
			•			5.00	***	

FIRST PILOT <u>J</u>	OSEPH B.	MATHIS II	I. Cant	0_748205 DES	TINATION	N Hanover.	
	VAME	I	RANK	ASN		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

1. Position of missing aircraft when last sighted or contacted:	1.	Position	of	missing	aircraft	when :	last	sighted	or	contacted	:
---	----	----------	----	---------	----------	--------	------	---------	----	-----------	---

(a) By coordinates App. 5250N-0223E

(b) Approximate altitude 12.000 feet

(c) Last noted heading \_\_\_\_ Crashed into sea

(d) If out of formation, approximate distance from formation \_\_\_\_\_\_ See No. 7

Describe enemy opposition (intensity of flak, intensity and method of enemy fighter attack, etc., with particular reference to missing A/C)

(vola in) the Cit None

3. Description of extent of damage to missing aircraft (including fires, explosions, etc):

Aircraft broke up and exploded

4. If aircraft was out of control describe appearance:

aircraft exploded after collision.

(over)

CONFIDENCE AL

Descript 1

## CONFIDENTIAL

5. If distressed airc				
with escort? No If	so, give di	stinguishi	ng marking	of fighter
group if noted (Group		r and or f	igi.tur.eire	roft
numbers, nicknames, et	0.,).	1 25		

6. Number of parachutes seen and description of jumps (approximate altitude, time between jumps, etc)

2 to 5 parachutes seen

7. Any other remarks not covered by above:

Aircraft No. 43-37976, Pilot, Capt Mathis, flying in \$4 position of high Sq. collided with lead aircraft of high Sq., and both planes went down with several crews reporting 5 chutes. At the time of the accident weather was clear, visibility was excellent and formation good. The lead aircraft reduced speed while in gradual climb, as evidenced by radio conversation between lead aircraft and Lt. H. Brown (witness) the latter asking the lead Pilot what has airspeed and lead pilot replying 140 mph. (see below)

-WITNESSES: NAM		RANK	ASN	A/C No.
BROWN HAROLD	(IMI)	1st Lt	0-764201	43-37598
			41 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		a design of	in the straight.	En Take

John M. KAVANAUGH,

O JOHN M. KAVANAUGH,

O JOHN M. KAVANAUGH,

O JOHN M. KAVANAUGH,

## CONFIDENTIAL

Remarks cont'd—At about this time Lt Mathis' aircraft overran slid ahead and under lead aircraft. Lt Mathis' aircraft held hhis position without losing altitude or making any attempt to clear. For about 10 seconds planes remained together then collided. Air Sea Rescue picked up three men from other crew. Two were dead and One was alife.