

Wed. - 20 - Oct. - 1943

0000,

All quiet - Watch continued.

0500

Ops. advises us of briefing for 0830 hrs. and also advises us of 8 visiting ak from Ridgewell to be here by 0700 hrs.

0759

8 visiting ak from Ridgewell landed & dispersed

0910

Attended briefing - Data follows:

R/W - N-S

Taxi - 1050

Stations - 1040

Take off - 1100

Codewords

O.C.S.

start Eng. Rene

367-NKZ 482-TH2

st'by Eng. Joan

368-PWC

Miss Delayer - Nancy

369-RBF

SCRubber - Sylvia

423-LLS

0945

All necessary calls made for Cletchers, tenders, etc.

1230

on duty Capt. Hally.

1240

wind South 26 mph.

1315

Made general inspection of airframe.

1405

wind SSE - 26 mph.

1430

our "Pandit" required down to down

1435

arrangements made for extra tenders - balloon
mops - Cletchers to be at tower by 1600.

1550

Issued Comm "W.B." to "Pandit" crew.

1840

called station engineer to check
fence posts on R/W 24 - (no lights or
scanner)

1845

"Pandit" crew reports everything OK.

2000

changed R/W to # 18 because of U/S fence
posts on # 24. Disputed airframe in
general.

2400

oil quiet.