

- 0330 Necessary calls made for 0410
0444 66 flares fired - one % ready.
443-14 - had % to take-off without radio op.
598-4 - 423 Spt. " " "
Doubt T.O. 6.01 by Capt. Sutton.
0603 Last able % airborne #198-D-369th %
0613 66 fired for Dog force 802 F just % off
575-X took off minus one tachometer & no
tail turret gunner
0706 last fog % off 572 A. 369th Spt.
0830 Off to Castille ON Capt Peterman
0930 Made routine inspection of gen. areas over
and submarine surveys. Off 441C on 30
W.E.P. on side of main R/W flying con stop
0943 clockwise with mes. They say wind from 22
E-S-E to S-E running clockwise with Pod. 7
Chelveston Pod on 05 - Chel. on 24.
1000 Change R/W TO 18
1120 Change R/W TO 18 - W/V = 3-S-E - 18.
1200 Last mission a/c down.
1200 ON duty - Lt. DASS OFF - CAPT. PETERMAN
1215 CAPT. PETERMAN attending briefing for
2nd. mission
1300 Inspected AIRFIELD - Pref room 865/2000
Times for 2nd mission
St. Eng. - 1350 TAXI - 1405 TO - 1415
ETA 19:59.
1430 All mission a/c off.
1530 No night flying.
1632 ETA - 19:59
1715 Off duty 17. Gass - on St. Flying
1900 Made airdrome inspection - now 900 &
pounds had also of oil obstructions. set
leaving for 06 sunrise.
Charged 6.8000 for landing permission
and - 5.00 - rough.
1945 All op. up down.

SUNDAY 25 MARCH 1945
0315 Departed 36 ops 710 AM of WIND S-SW.

	1000	11,811	Low	
SE	0507	0513	0519	
Top'	0522	0528	0534	40 th - 3
Tp	0537	0543	0549	

Here are (3) three new positions for dropping bombs today if need arises. Positions A, B, & C may be obtained from 1st B. Div.

0711 Gp. advised best of our Atk. PW changes to 24. W/V. 55A-8. Lights on - R/H Inspected.

0800 181-B - 368 Sgds. caught fire in t. on landing. - Tanks off. No. 2120

0800 ON duty - H.T. BASS OFF - Capt. KETTERMAN

0900 Inspected AIRFIELD - OK.

0930 028 "O" 368 Sgds. landed at Blackbrush - R.D. 1 in to weather which is deteriorating rapidly in that area.

1100 028 "O" is returning to base.

1200 028 "O" landed from Blackbrush.

1200 On duty H. battle off Lt. Bass.

1210 Inspected airfield - outcome Uncertain.

No 028 stuck just off perimeter by surprise

44-368 informed to remove No. Capted 2500
in S.E. end of 30 ft. w.

1300 ON duty - H.T. BASS OFF - H.T. CARLIE

1815 Inspected AIRFIELD - OK.

2000 Standby

MONDAY 26 MARCH '45

0300 STANDBY STAND down

0415 ALERTED. Neither Adm. nor Chet. ARE doing ANYTHING AT THIS POINT.

0605 Briefed 86 APC on 06 T.O.

HEAD	H.I.	HO
------	------	----

START	0844	0850	0856
-------	------	------	------

TAXI	0859	0905	0911
------	------	------	------

- T.O.	0909	0915	0921
--------	------	------	------

H.T. T.O. - 09:55 Ref. Atk. - 18,000

ZERO HOUR - 1900 WX CD. - TIVAD

Fox hole ABHs E.T.A. - ?

0115 Inspected AIRFIELD - free from obstructions.

0800 On duty H. battle off Lt. Bass.

0814 Mission completed with 62% fuel left.