

ON MAIN R/W) - ORDER of Col. Kestling.
SIGNIFIED TO AIR MINISTRY. F.C. NOTIFIED

- 1830 Off duty Lt. Bass - on Lt. Blaize
1845 Made audience inspection - main R/W +
perimeter clear of obstructions - successful.
30 W.E.S. 45

- 0800 ON DUTY - LT. BASS OFF - LT. BLAISE
0805 INSPECTED AIRFIELD - FREE FROM OBSTRUCTION
0905 Station engines in runs - airbone lighting
will be off today. lighting will be on tonight.
Lower lighting will not be affected
1000 124-4 Pilot Smith made very rough
landing. Told to check tail wheel before
landing again.
0905 124-4 landed very rough again off end
of R/W. Pilot warned of poor visibility
offend and to land a little longer. Pilot
informed to check complete landing gear
before attempting another landing
1100 Gp. Ops. To be notified 1HR. IN ADVANCE
WHEN SCS-51 is to be turned on.
1200 On Lt. Carlile off Lt. Bass
1300 Inspected airbone - WTP. R/W 30 +
perimeter by Cheveron.
1330 ON DUTY - LT. BASS OFF - LT. CARRIGE
1340 INSPECTED AIRFIELD FREE FROM OBSTRUCTION

May 31, 1945

- 0800 On Lt. Carlile off Lt. Bass
0830 Inspected airbone - WTP 368th and perimeter
and short R/W's
1330 Off duty Lt. Carlile - on Lt. Blaize
1345 Made audience inspection - all OK.
Note Col. Upton is departing at 8-10 AM today
or tomorrow morning. He will be aware
of the need of bad signs - immediately.
On Lt. Carlile off Lt. Blaize.
1350 Inspected airbone - Hole in perimeter
track in 368 area.
1440 Contact steps W/S T.F.N. F.C. ops. NOTIFIED
D/A NOTIFIED
2100 % Rockford J-Ts called Shurley for