

- 0310 Checked lighting on Nov 30 - 5 with exception of top light on left side, they are covered with grass.
- 0408 124-W - WX etc off on 30 Nov
- 0634 Capt. Lacey Jones a/c off.
- 0745 Off Lt. Carlisle
- 0800 On Lt. Blaise Off Lt. Carlisle
- 1200 Off Lt. Blaise On Lt. Arpin
- 1300 Aerodrome O.K.
- 1510 Off Lt. Arpin - on Lt. Jones
- 1525 Col. Latham & Col. Hering A.O.N. Stratford (C-48)
- 1530 Make random inspection - Nov 30, & make Nov 29
- summary sheet of obs. & serviceable.

July 29 July 1945

- 0350 WX ship off.
- 0446 WX ship landed due to radio trouble. Capt. Smith (423rd) replaced 764 with 474 E. Capt. Lips & Dix will be notified of change at 710 Unit.
- 0510 Rad. & Log. notified of change. (Ship not off)
- 0535 WX ship 474 E off.
- 0800 Off Watch Blaise On Watch Arpin
- 0910 Aerodrome O.K.
- 1505 Pelos flying R-25 over tomorrow is to get instructions at R-25 about Lt. Col. Mason.

- 1230 On Lt. Carlisle off Lt. Arpin.
- 1300 Inspected airframe - S
- 1715 R/W changed to 24 72.5 to SW wind W-12 (Variable toward SW).
- 1800 Off Watch Carlisle On Arpin
- 1910 Aerodrome O.K.
- 2145 Lighting checked. O.K.

July 30, 1945 - Memory

- 0330 WX a/c off.
- 0735 On Lt. Carlisle off Lt. Arpin FT NIL
- 0805 368th Scudged Capt. Jones
- 0845 Inspected airframe - S
- 1100 HF DIF asked to send out weather every 15 min until we tell them to stop.
- 1320 Off duty Lt. Carlisle - on Lt. Blaise
- 1410 Make random inspection - main Nov and