

bombing tasks place here.

0745 30 ship practice formation in morning to Germany.

April 29, 1945 Sunday.

0745 Eight operational F's from 369th Sqd. 1:0. 1030 hrs.
O.C.S. TVK. R/W 36. Wind W. 15-20 M.R.H.

0800 Off Lt. Bass - on Lt. Blaine

0810 Made audience inspection - H/W 30 clear of
all obstructions and serviceable - personnel S.

1049 369th Ops 1/c off. Gp. Ops. instructed us to
inform 838 F & 652 R by HF-DF that they
will be fighter support.

1100 HF-DF could not contact other ship on HF-DF
Instructed VHF-DR to transmit to both
ships to listen out on HF-DF.

1115 838 F & 652 R acknowledged transmission
on HF-DF. Gp. Ops. informed.

Note 838 & 652 are the only ship going over
enemy held territory.

1140 Gladdon is sending 2 ships to provide cover
at 1000 hrs.

1230 On duty - Lt. Bass Off - Lt. Blaine

1235 Inspected AIRFIELD - free from obstructions

1235 R/W changed to 36.

1340 German informs us flight of HAC 150-B to
Y-75 is OK for 7:0 at 0700 hrs.

1700 A/C 772 is going to drop paracutre bombs on
field from 400 ft. Div. informed

1800 Off duty Lt. Bass - on Lt. Blaine

1800 A/C 858 R returned from Ops. All consumed
noticed. Crew to intelligence and Gp. Ops.

2000 Made audience inspection - main R/W & R/W
to clear & serviceable. Instructed task OK - Too!

2200 Gp. Ops. informs me there will be an 8 ship
mission tomorrow. Fuel details not known.
Times as follows: - Briefing 0915 - start
engine 0930 - tax 1000 - 70 1000. At 7:45, engine
is to be present. No cap plane needed.

MONDAY APRIL 30, 1945

0700 Change of 0800 to

0800 Off duty Lt. Bass - on Lt. Bass.

- 0515 Attended briefing for 7 ops. A/C. 10.10K
0830 Inspected R/Ws & perimeter - free from obstruction.
1020 A/C 7720 has been instructed by W/T to RETURN TO BASE - ORDERS of Col. Upham.
1000 Col. UPHAM IN 4543 RETURNED TO BASE - 10.10K
1230 On Lt. Barile off Lt. Bass.
1315 Inspected audience and changed 11/w to 36 STO. Wind N.W. 14
1559 896X last ops 2
1615 Maj. Witt re-disposing of A/C from 361 Clovers Hatch (14-15-16-17) to various ports on grass between areas - 14-20-21. Clerk of Works to begin work on week 52 closer 15 MAY (100s) should be on for 3 days.
1620 6 A/C for night flying. Briefing 2013
1800 AT-6 - #604 landed - lost. Cleared to Cheddington returning to Leaden. Cheddington called.
1834 AT-6 audience for Leaden - Leaden called.
1930 ON DUTY - Lt. BASS Off - Lt. CARRIGE
1835 Inspected Airfield - free from obstruction
NOTE - 2200 454 & F11B-DUB ARE BOTH SCRUGGED FOR TOMORROW. - (Sgt. Hind - Sp. Gp.)
2245 AP 376 F blew tire while taxying out for T.D. at 2045. Much trouble experienced in getting tire change crew. AP not fixed until 2245.
2320 NIGHT FLYING OVER.
08 May 1, 1945 - Tuesday
0800 On duty Lt. Barile off Lt. Bass.
0900 Inspected audience - Changed 11/w to 30
0953 11/w changed to 36
1005 In formation from 28 sqd. this afternoon clearance to be sent up to two half hours before 1.0. S.T.D. 1400 hrs.
1200 Off duty Lt. Barile - on Lt. Bass
1300 Made audience inspection - 11/w 30 a - spuds