

JAN 7<sup>th</sup>

1000 T.O.W Capt Hartnell.

DHOME RED.

- 1230 H.O.W Capt Hartnell T.O.W Lt. Eagle.
- 1300 Ops inform 1st A/c Left St-Eval for Thurlog C 11.42
- 1305 Beacon Still on Runway Beam switched on
- 1306 1st Lt. Beaching 1st Wing informed DHOME unfit. too few humans  
~~fat~~ fat & ceiling practically zero. he advised wait  
instructions.
- 1310 Major Oliver advised agreed DHOME unfit for Plane  
to Land.
- 1330 Wing advise A/c may be diverted to Port Raith or  
Gredanwick A/c that come overhead stand by for  
definite instructions Met five QFE 29-48 998.1 nos 5.
- 1350 Wing gave sanction to any A/c wanting to come in  
in beam if they feel capable DF to get endurance  
of plane Messages passed to DR.
- 1415 A/c now overhead 1st Wing advise A/c should return  
to either St-Eval or Davidstone
- Q367 acknowledged message A/c returns to St-Eval  
Major Oliver who was in Watch office at this time  
acquainted with above procedure as unpossible to

AC TIME

1600

NARRATIVES

TOM COOK-TARRELL.